

3D Imaging Dome Prototype

Second Round of Prototype Tests
And Some Modifications


Sanha Cheong

SLAC MAGIS Group Meeting
Aug. 5th, 2021



MDProto2: Review




- Reflects lessons learned from MDProto1
- Object rod now has a knob for easy handling
- Local support board & base board separated
 - Base can stay on the optical table
 - **LS board can be printed face-up**, hopefully leading to better quality
- Parameters tested:
 - Hole diameter: 5.2mm
 - Front-stop overlap: {0.2, 0.3, 0.4} mm




MDProto2: Products Arrived

Arrived on Monday, Aug. 2nd

- **Black opaque material**
 - Different material called “Somos Taurus”
 - “... I thought that you were in a rush for this part and that machine was open.”
 - Seems slightly tighter, but not a major issue
- Local support board
 - Seems to be better quality overall, particularly the “knobs”
 - **Printing orientation seems to have helped!**




MDProto2: Local Support Board



MDProto2: Mirror Loading Experience

- All 5.2mm holes, still **loose**
 - Transverse movement
 - Not a major issue by itself,
 - But, combined with axial movement
⇒ Can cause alignment errors
- **Visible axial movements**
 - Particularly among inner mirrors
 - Hints at back knobs not pushing in properly
 - In MDProto1, edge mirrors had loose axial pressures
 - Mainly attributed to back knob print quality




MDProto2: Imaging Attempt

What is being done here:

- All 23 mirrors loaded
- Imaging a tiny LED ($< 1\text{mm}$)
- Tapping the dome to create some disturbances

What we see:

- Significant alignment shifts in inner ~ 10 mirrors



MDProto2: Debugging the Issue



Potential Cause 1:

- The back knobs are simply not long enough to push the mirrors actively
- Too much axial room

Potential Cause 2:

- Front & back boards are screwed only at the edges
- This could flex the board towards the edge
- Better contact at the outer mirrors, looser contact at the inner mirrors

Could be a combination of both (and more) causes



MDProto2: Addressing the Potential Causes

Addressing potential cause 1:

- Make the back knobs longer
- Two adjusted versions
 - +0.5mm back knobs at all locations
 - +0.5mm back knobs at inner 10 locations only

Addressing potential cause 2:

- Add a screw at the center for more even pressure
- Can use the existing hole (originally for object rod)
 - Current design: 3.2mm diameter hole
 - Use long M2.5-0.45 or M3-0.50 screw + nut
- No adjustment required for the print, just need some screws

Summary

- MDPProto2 arrived & briefly tested
 - Still some issues with mirror alignments
 - Seems like some mirrors are not being pushed well (inner ~10)
 - Some room in both transverse & axial directions
- Trying to address the axial issue first
 - Make the back-knobs longer
 - Add a screw at the center to prevent board flexing
 - Buy another pack of screws?
 - Can we get a few from somewhere within SLAC
- New design files sent to Ariel on Wednesday, August 4th
 - Should be able to test some time next week